

PORT OF WORKINGTON

SURVEY NOTICE NO. 5 of 2020

To Port of Workington Users

Attached is the latest survey data for the Port of Workington approach channel & turning basin dated 9th September 2020. This survey data shows where siltation has occurred.

Please note that the depths shown are relative to the Prince of Wales Dock sill at 1.16 metres below chart datum.

Users should note that tidal flows and weather conditions can result in fluctuations in water levels and sea bed depths within the harbour and its approaches.

Vessel operators are reminded that at all times they must allow sufficient under keel clearance to safely navigate within the Port of Workington's jurisdiction.

If users are in any doubt as to the safe under keel clearance and available water depths they should contact the Port of Workington Harbour Master.

R. Oldfield

Harbour Master

11th September 2020